

N2H2 function disappear after update to version 076.032.040



Affected

ACS 753/763/863 - AC1234-7i/1234-8i/1x34-7i with manual update to version 076.032.040.

Brand	Units	Refrigerant type
Bosch	ACS 753	R134a
Bosch	ACS 763	1234yf
Bosch	ACS 863	1234yf
Robinair	AC1X34-7i	R134a
Robinair	AC1234-7i	1234yf
Robinair	AC1234-8i	1234yf
Robinair	AC1234-8i NX	1234yf

i Function disappear **ONLY after update to version 076.032.040.**
The units produced with that version AREN'T affected and don't need the field solution above.

Remedy

- 1) Copy software version 076.032.041 from EDIS or Download area to an USB-Stick.
- 2) Put this USB-Stick in the AC unit.
- 3) Search for Update ((Stand-by page, Setting Menu, Search for Update)).

i The update process once starts take less than 2 minutes.

You will find the software in EDIS:

Bosch: \edis\software\systemsw\acs6xx_7xx\acs753_763_863

Robinair: \edis\robinair\software\systemsw\ac1234-7i_ac1234-8i

Robinair: \edis\robinair\software\systemsw\ac1x34-7i